SERVICE REPORT



SECTION 1 – COMPLETED BY PSI CONTACT	FIELD SERVICE TRACKING #:			
CUSTOMER: C.F. Roark ADDRESS: 136 North Green ST.	ORIGINATION DATE: PSI CONTACT: Richard Robinson			
CITY: Brownsburg CONTACT Bradley Beeson	STATE <u>IN</u> <u>ZIP CODE 46112</u> CUSTOMER P.O.: 033528-00			
PHONE: (317) 852-3163 PAR	RT/MACHINE NO: 10251			
SERVICE REQUEST DATE: 5-10-11 SER	RVICE SCHEDULE DATE:			
DESCRIPTION OF SERVICE REQUESTED BY CUSTOMER:				
INSTALLATION WARRANTY 1 - Welder arcing out	NON-WARRANTY ■			
2 - Filament very un-stable 3 - Perform preventive maintenance 4 - Perform 6 month calibration				
SECTION 2 – COMPLETED BY SERVICE REPRESENTATIVE				
A. DATE / TIME SERVICE BEGAN: 5-10-11 12:00pm	ENDED: 5-13-11			
 B. DESCRIPTION OF SERVICE / ACCOMPLISHMENTS PERFORMED: 1 - The EB gun and corona ring were both removed and cleaned. There were evidence of major arcing on both. The major arcing issue has been resolved. 2 - The PM and Machine calibrations has been performed. Brad has both reports. 3 - The EB Welder is back in full production. 4 - I would also like to recommend that Roark request that the polycoly unit receive a check-up 				
C. (NEW ISSUES) DURING PERFORMANCE OF SERVICE				
1 - During PM it was dicovered that the A side diffusion pump has a bad circuit breaker. 804 cb and possibly a bad heater. (repair is in progress) 804 cb has been replaced. The diffusion pump currents are as follows. 13 amp 10 amp and 10 amp. Should be 13 amp for all legs. The customer will replace the heaters.				
2 - Brad informed me that the optics p.c board returned from Sciaky to Roark still is having issues. The board must be checked and verified for final alignment on the welder. Should be performed before and emergency happens. The scheduling can be worked out between Sciaky and Roark.				
3 - Replaced the secondary diodes in the high voltage tank, replaced ground strap connected to the high voltage tank.	ed the bias resister inside the tank, replaced the			
D. ADDITIONAL PARTS / RESOURCES REQUIRED				

SERVICE REPORT



The customer has make a request to Sciaky to order a new gun cartridge. Ron has the information.

PART NUMBER	DESCRIPTION		QUANTITY		
E. SITE LOCATION:					
Algorithment	DATE OUT	5-13-11			
	IME OUT	2:00pm	TOTAL HOURS ON	SITE 34	
F. CUSTOMER CONTACT	. 115		1. 1 1	N SITE	YES NO
CUSTOMER SIGNATURE:	Dra	dly 11.	Beeson		
CUSTOMER COMMENTS:					
G. FOLLOW-UP SERVICE	REQUIRED	⊠ NO	YES		
IF YES, DESCRIBE:					
H. PROGRESS / STATUS REVIEW WITH CUSTOMER AND PSI MANAGEMENT (DAILY) FOR EXTENDED PERIODS OF SERVICE					
	LOCATION		FOLLOV	V-UP NO	
PSI CONTACT NAME	_				
REVIEW RESULTS:					
	*				
BILL TO					
CUSTOMER:					

00		7 -	4 5	7	
US		(.5	.4 t	ĸе۱	/. C

SERVICE REPORT



ADDRESS:						
CITY:	STATE:	ZIP:				
EB RW FU Misc. FS Job No.						
CHARGES						
TRAVEL HOURS _12 =						
LABOR HOURS (Normal)						
LABOR HOURS (Overtime) @ =						
LABOR HOURS (Double Time) @ =						
PER DIEM (DAYS) @ =						
CAR RENTAL =						
AIR FARE =						
MISCELLANEOUS						
=						
=						
TOTAL =						
SERVICE DED SIGNATURE OR NAME:	6-13	-11				
CUSTOMER CONTACT SIGNATURE OR NAME: Drudley & Bonson						
COSTOWER CONTACT SIGNATURE OF NAIVIE.	or recessor					
SECTION 3 – COMPLETED BY DIVISION MANAGEMENT OR DESIGNI	EE					
A. DID SERVICE BEGIN AS SCHEDULED?		YES NO N/A				
B. WERE SERVICE OBJECTIVES ACCOMPLISHED?						
C. WERE ALL ADDITIONAL ISSUES ADDRESSED?						
D. WERE ALL ADDITIONAL PARTS/RESOURCES NEEDS ADDRESSED?						
E. IF REQUIRED, HAS FOLLOW-UP SERVICE BEEN SCHEDULED? F. WAS PROGRESS ON SCHEDULE AND STATUS REVIEWED WITH CUSTOMER?						
G. DID CUSTOMER CONTACT WITNESS FUNCTIONALITY OF EQUIPMENT?						
H. WAS CUSTOMER SATISFIED BASED ON THAT DOCUMENTED REVIEW?						
DIVISION MANAGER OR DESIGNEE:		/				
SIGNATURE: Bradley a Beeson	DATE:	5/13/2011				

QSF-7.5.4 Rev. C

SERVICE REPORT



Distribution: GENERAL MANAGER OR DESIGNEE AND APPLICABLE SALES REP. OR TERRITORY MANAGER